

# ACRYTHINNER X 34

FADE OUT FOR SHADING WITH LOW VOC CONTENT

## substrate pre-treatment



mat the surface to be faded out

degrease with silicone remover

## application



mix the 2k product 1 : 1 in spray gun with ACRYTHINNER X 34 and apply over the mat surface to be treated.  
apply the thinner as it is and effect fading out

Remark:

Fading out has to be effected inside the mat area

---

*The information given in this technical data sheet is based on present scientific and technical knowledge and thus do not exempt the customer to test the suitability of our products for the use and for the intended purposes.*

**EP vernici s.r.l.**

Via Roma,12 I-48027 Solarolo (RA) tel.+39 0546 53322 fax +39 0546 53323 email: laboratorio@epvernici.it [www.epvernici.it](http://www.epvernici.it)

